

## **BVMS 13.1 hotfixes**

Date:  
**25 August 2026**

## BVMS 13.1 - Cumulative Patch history

| No. | Patch version      | Release Date |
|-----|--------------------|--------------|
| 1   | Cumulative Patch 1 | 13.02.2026   |
| 2   | Cumulative Patch 2 | 25.02.2026   |
| 3   | Cumulative Patch 3 | 26.05.2026   |
| 4   | Cumulative Patch 4 | 07.07.2026   |
| 5   | Cumulative Patch 5 | 21.08.2026   |

## Cumulative Patch 5 for BVMS 13.1

### Overview

| No. | Name of the fix                                                                       | Included in                |
|-----|---------------------------------------------------------------------------------------|----------------------------|
| 1   | 497970 - Bug in ConfigClient with add camera                                          | Cumulative Patch 5,4,3,2,1 |
| 2   | 498250 - Motion export issues with VSG RTSP camera to none-native format              | Cumulative Patch 5,4,3,2,1 |
| 3   | 498363 - Security improvement                                                         | Cumulative Patch 5,4,3,2   |
| 4   | 504329 - License plate with letters ÄÖÜ can not be added to list in BVMS              | Cumulative Patch 5,4,3     |
| 5   | 503198 - IVA Pro Context Events are always fired when camera configuration is changed | Cumulative Patch 5,4,3     |
| 6   | 503162 - Secured connection might not work for some Axis devices                      | Cumulative Patch 5,4       |
| 7   | 503887 - Audio not working correctly for VSG live cameras                             | Cumulative Patch 5,4       |
| 8   | 505208 - Random issues with playback of available recordings                          | Cumulative Patch 5         |

| No. | Name of the fix                              | Included in        |
|-----|----------------------------------------------|--------------------|
| 9   | 505595 - Disconnections between BVMS and BIS | Cumulative Patch 5 |

## Detailed Release Notes for the patch

|                              |                                                                        |
|------------------------------|------------------------------------------------------------------------|
| <b>Patch ID:</b>             | 505208, 505595, 503162, 503887, 504329, 503198, 498250, 497970, 498363 |
| <b>Patch Title:</b>          | BVMS 13.1 - Cumulative Patch 5                                         |
| <b>Patch Target Version:</b> | BVMS-13.1.0.255                                                        |

### Patch Details:

#### Cumulative Patch 5:

This patch fixes issue 505208 in playback on the Operator Client.

This patch fixes issue 505595 in disconnection between BVMS to BIS.

#### Cumulative Patch 4:

This patch fixes issue 503162 in which some Axis cameras are not working with secure ONVIF connection.

This patch fixes issue 503887 in which audio is not working on VSG live mode.

This patch needs the Video Streaming Gateway version 9.4.8.1 to work properly.

#### Cumulative Patch 3:

This patch fixes issue 504329 with improvement regarding license plate with letters that cannot be added to list.

This patch fixes issue 503198 with improvement regarding Pro Context Events being fired when camera configuration is changed.

#### Cumulative Patch 2:

This patch fixes issue 498363 with a common security improvement.

#### Cumulative Patch 1:

This patch fixes issue 498250 that Motion export with VSG RTSP camera to none-native format is working as expected.

This patch fixes issue 497970 in Configuration Client by closing the add encoder dialog correctly.

### Problem Details:

#### Cumulative Patch 5:

Issue 505208 caused a problem on the playback in the Operator Client.

Issue 505595 caused a problem regarding the disconnection between BVMS to BIS.

#### Cumulative Patch 4:

Issue 503162 caused a problem that some Axis cameras are not working with secure ONVIF connection.

Issue 503887 caused a problem that audio was not working on VSG live mode.

## Cumulative Patch 3:

Issue 504329 caused a common problem with license plate with letters that cannot be added to list.  
Issue 503198 caused a common problem related to Pro Context Events being fired when camera configuration is changed.

## Cumulative Patch 2:

Issue 498363 caused a common problem.

## Cumulative Patch 1:

Issue 498250 caused the problem that Motion export with VSG RTSP camera to none-native format is not working as expected.

Issue 497970 caused the problem in Configuration Client to add the same camera multiple times (also in the Device Tree).

## Affected Bosch VMS Components / Machines:

- BVMS Management Server
- BVMS Operator Client
- BVMS Configuration Client
- BVMS Cameo SDK

## List of Replaced Files:

- Bosch.HostApplication.Api.Support.dll [Version 13.1.0.258]
- Bosch.Vms.BISProxy [Version 13.1.0.263]
- Bosch.Vms.Client.Shared.StreamVisualization [Version 13.1.0.262]
- Bosch.Vms.Frontend.ConfigClient.Common.Wpf.dll [Version 13.1.0.256]
- Bosch.Vms.Frontend.OpClient.LicensePlateManagement.Wpf.dll [Version 13.1.0.258]
- Bosch.Vms.Shared.Export.Mpeg.FfMpegFacade.dll [Version 13.1.0.257]
- OperatorClient.exe [Version 13.1.0.258]
- OperatorClient.Supervisor.exe [Version 13.1.0.258]
- BVMSOpcServer.exe [Version 13.1.0.263]
- GCA2.dll [Version 6.70.8.29738]
- ONVIF\_VDP.dll [Version 3.9.0.2]
- rcppmedia.dll [Version 3.50.7.0]
- ONVIF\_VDP.dll [Version 3.9.0.2]