Product: AMS 5.0.1

Location/Date: Aachen/April 2023

Patch:

- AMC2 - Wiegand

- Patch details:

  Fix a possible problem in the processing of the AMC Wiegand Interface, where AMC is trying to process invalid data from reader interface.

Patch file details :

LCMV3772_v02.39.01_Wiegand.zip

SHA256: AD3052F1B017D8F88471997A7F0D47F2F2231D3920579CCC47BA15537DDD7220

TFS: #TFS389156

Update procedure:

Patch on server

1. Navigate on all MAC to Installfolder   (e.g on BIS/AMS System Installfolder/AccessEngine/MAC/bin

2. Rename LCMVXXXX.run to LCMVXXXX.run.org

3. Copy LCMVXXXX.run to folder

4. Reset the AMC to Booloader (Use ResertButton or send command Coldstart on AMC with AMS MapView or BISClassic client)

NOTE:

Patch files must be removed manually before upgrading to the next version to avoid problems with the upgrade process.

The same applies if you try to uninstall. In this case, the files must be removed manually.