

From		Nuremberg
BT-VS/XSW-AIA	Product Management	19.10.2023

## Release Letter

Product:	<b><i>Bosch Forensic Search for Genetec Security Center</i></b>
Version:	<b><i>1.0.2</i></b>

This letter contains latest information about the above-mentioned software.

### 1 General

For swift and precise incident retrieval, the Forensic Search Plug-in seamlessly integrates with Genetec Security Center. It uses Bosch IVA Pro metadata which is already present on all cameras by default. There is no need for additional hardware, and it is fully compatible with all Bosch cameras.

### 2 Features

The following features are available under the 'Investigations' section in Security Center:

#### Bosch Forensic Search:

- Retrospectively investigate incidents that you were not aware at the fact
- Supports all Bosch IVA rules applicable to the forensic search
- Interactive timeline representation of the search results
- Further investigate search results through bookmarking or CSV export

### 3 Versions

- 1.0.2: Bugfix release
  - Fixes an issue with certain Windows localizations.
  - Fixes an issue that led to a crash in conjunction with other plugins being installed on the same system.
  - Fixes an issue that occurred with duplicated Genetec database entries for the camera identifiers.

From BT-VS/XSW-AIA	Product Management	Nuremberg 19.10.2023
-----------------------	--------------------	-------------------------

- Fixes an issue where the camera tree of the Forensic Search was not loaded after a restart of Security Desk.
- Fixes an issue where counter rules were not delivering any results.
- 1.0.0: Initial release

#### 4 Restrictions, known issues

- The hybrid driver ['Other (CPP13 and newer)'] on SC 5.11 from device pack 11.3 and 11.4 need an addition archiver setting to record the Bosch metadata stream appropriately for the forensic search to be functional. The advanced setting that is needed for the Archiver is: *BoschHybridDriverVcaMetadata=true*
- To operate the plugin in **SC 5.11** (5.10) an additional free of charge license from Genetec is needed. The necessary license to be ordered from Genetec is: GSC-1SDK-BOSCH-PLUGINSUITE with 5 connections.
- Only on instance of the server plugin should be active and installed.
- A maximum of 10 cameras can be processed in parallel.

#### 5 System Requirements

Minimum System Requirements	Description
<b>Operating System</b>	<ul style="list-style-type: none"> <li>● Windows 10</li> <li>● Windows 11</li> </ul>
<b>Genetec Security Center</b>	<ul style="list-style-type: none"> <li>● SC 5.10.4 and above (for SC 5.10 release)</li> <li>● SC 5.11.3 and above (for SC 5.11 release)</li> <li>● 'Legacy (CPP7.3 and older)' driver or 'Other (CPP13 and newer)' driver from Device Pack 11.3 or above</li> <li>● Security Desk - 64bit</li> </ul>
<b>Camera</b>	A Bosch analytics camera (with firmware version 6.32 or above), connected to the Genetec Security Center